ECS Configuration Change Koquest				Page 1 of / Pages
CCR No. 98-0385 Logged	Date 3/30/98	Rev	Request T	(, , , , , , , , , , , , , , , , , , ,
Priority Routine X Urgent	Emergency	Affected Release	B.0	Change Class # I
Title (description) G0dmh01 relocation from S1310 to C101C console #32				
Cable Configuration Management Plan 920 -TDG-005 Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or Tech Reference Ceroz GDAAC Physical Floor Plan 920 TDG-004 Rev. 02 None.				
	5-004 Kev: 02	None.		+ <u>1</u>
RTM Change Start New Bas	seline 🗌			
Problem G0dmh01 which is located in S1310, has no current operator.				
Proposed Solution Move G0dmh01 to C101C console #32 until it is clear who will be utilizing this machine during operations. It may go out to a cubicle to support a TBD data specialist person later on in a TBD cubicle.				
Impact Analysis:				
Organizations Affected: BOO	Contracts E	CS Chief Eng	FOS 🗀	M&O X
Procurement QO Science Off Security	Rel. Dev Subcontrot	Rel. B 🗓 Sys. Eng 🦳	Rel. C	SCDO Arch.
Cost: None x	Small	Medium 🗍	Acpt Large	
_	(Not exceeding \$100,000)	(\$100,000 to \$500,000)	(Over \$500,000)	
Schedule: None X	Other		27/4	
Additional LOC N/A		Man-Months	s <u>N/A</u>	
Materials N/A				
Originator Eric Obligacion	Pic	()	<u> </u>	376 98
GDAAC Local Maintenance Coordinator	Signature	A O .	/	Date S/
Office Tom Dopplick Office Manager GDAAC M&O Manager	Signature	Jopplus		3/27/98 pate
Disposition Approved	Approved w/Comm	nent 🔀 Forw	ard $oldsymbol{oldsymbol{oldsymbol{eta}}}_{\mathcal{N}}$	Disapproved
Comments: All work	to be paid	for by Si	RB. NO	SEM. WBS
CCB Chairperson	Signature	ily		4/13/98 Date
CM01OC96	Опунацие			ECS

ORIGINAL